Approved For Release 2002/06/13 : CIA-RDP81B00876R000800090011±6

20 May 1960

SUBJECT: FOO Requirements for Contractor Technical

Service Personnel During FY-1961

TO:

Contracting Officer

187 Fale

The following represents FOO's requirements for technical services in support of FY-1961 operations:

a. Lookheed (SO-58): Four aircraft technical representatives will be required, as well as one Lear field engineer, in support of the autopilot system.

b. Rano-Wooldridge (HF-A-104): Two engineers and three technicians will be required by Laughlin. In addition, IPC will require the continued services of engineer, at UBAFE and of technician, (replacement for FEAF: The 15% domestic dislocation allowance should be eliminated from this contract.

25X1A

25X1A

- o. Hycon (HTR-88): Two senior field service engineers will be required.
- d. Perkin-Elser (TR-57): One field cervice engineer will be required.

e. Firewel (HF-AP-1940): The services of senior service coordinator, will be required.

f. Westinghouse (HF-8142); Four contract technical service personnel will be required.

It is requested that appropriate action be taken to contractually cover the technical services outlined above for FT-1961. Initial ... fund allothents in support of tech rep and other FOO contracts are being forwarded by separate letter.

25X1À	<i>C</i> .	K A	T_{ij}	

WES : maw

-DOCUMENT NO NO CHANGE IN CLASS. IJ F) DECLASSIFICE CLASS, CHANGED TO. IS NEXT REVIEW DATE: AUTh. Hr 70.2 DATE 16/2 Y/ BEVIEWER 0 095

Approved For Release 2002/06/13: CIA-RDP81B00878R000800090011-8

25X1A 25X1A

Next 1 Page(s) In Document Exempt